
Main Cross Sections
Elastic
Capture
Inelastic
cross section (barn)
neutron energy(eV)
10^3
10^2
10^1
10^0
10^-1
10^-2
10^-3
10^-5 10^-4 10^-3 10^-2 10^-1 10^0 10^1 10^2 10^3 10^4 10^5 10^6 10^7 10^8


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_2n
n_na
n_np
n_n_1
n_n_2
n_n_3
n_n_4


Cross Section
cross section (barn)
10-1
10-2
10-3
n_n_5
n_n_6
n_n_7
n_n_8
n_n_9
n_n_10
n_n_11
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_n_12
n_n_13
n_n_14
n_n_15
n_n_16
n_n_17
n_n_18


Cross Section
cross section (barn)
10^{0}
10^{-1}
10^{-2}
10^{-3}
n_n_19
n_n_20
n_n_21
n_n_22
n_n_cont
n_n_tot
n_p_tot
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^{6}
neutron energy(eV)


Cross Section
n_d_tot
n_He3_tot
n_a_tot
cross section (barn)
10-2
10-3
10-4
10-5
10-6
10-7
10-8
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Angular distribution (CMS)
Elastic
probability
10^{1}
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_2n part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_2n part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_na part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_na part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_na part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_np part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_np part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_np part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_1
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_2
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_3
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_4
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_5
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_6
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_7
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_8
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_9
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_10
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_11
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_12
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_13
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_14
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_15
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_16
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_17
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_18
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_19
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_20
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_21
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_22
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
neutron energy (eV)
*10^6


Angular distribution (LABS)
n_n_cont part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_n_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_p_tot part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_p_tot part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_a_tot part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_a_tot part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_2n part.=neutron
probability
10^0
10^{-2}
0
2
4
6
8
10
12
*10^6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_2n part.=gamma
probability
10^{0}
10^{-2}
0
2
4
6
8
10
12
*10^6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_na part.=neutron
probability
10^1
10^-1
0
energy (eV)
5
10
15
*10^6
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_na part.=alpha
probability
10^{1}
10^{0}
10^{-1}
0
5
10
15
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_na part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
2
4
6
8
10
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_np part.=neutron
probability
10^{1}
10^{-1}
0
5
10
15
energy (eV)
*10^6
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (LABS)
n_np part.=proton
probability
10^{1}
10^{-1}
0
5
10
15
energy (eV)
*10^6
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (LABS)
n_np part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
2
4
6
8
10
energy (eV)
*10^6
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_n_1
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_2
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_3
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_4
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_5
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_6
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_7
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_8
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_9
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_10
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_11
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_12
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_13
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_14
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_15
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_16
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_17
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_18
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_19
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_20
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_21
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_22
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (LABS)
n_n_cont part.=neutron
probability
10^1
10^0
10^-1
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_n_cont part.=gamma
probability
10^{0}
10^{-2}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_p_tot part.=proton
probability
10^{1}
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_p_tot part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
5
10
15
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_a_tot part.=alpha
probability
10^{1}
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_a_tot part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
5
10
15
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Gamma energy distribution
Capture
probability
0
5
10
15
20
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
*10^6


Gamma angles distribution
Capture
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
neutron energy (eV)
*10^6

Gamma multiplicities distribution
Capture




Gamma energy distribution
n_n_1
probability
100
50
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_1
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_1




Gamma energy distribution
n_n_2
probability
100
50
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_2
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_2




Gamma energy distribution
n_n_3
probability
100
80
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_3
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
neutron energy (eV)
*10^6

Gamma multiplicities distribution
n_n_3




Gamma energy distribution
n_n_4
probability
0
20
40
60
80
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
5
10
15
20
*10^6


Gamma angles distribution
n_n_4
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_4




Gamma energy distribution
n_n_5
probability
100
80
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
5
10
15
20
*10^6


Gamma angles distribution
n_n_5
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_5




Gamma energy distribution
n_n_6
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_6
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_6




Gamma energy distribution
n_n_7
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_7
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_7




Gamma energy distribution
n_n_8
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_8
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_8




Gamma energy distribution
n_n_9
probability
0
10
20
30
40
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_9
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Gamma multiplicities distribution
n_n_9
probability
20
15
10
5
0.5
1.0
1.5
2.0
2.5
multiplicity
0
5
10
15
20
*10^6
neutron energy (eV)


Gamma energy distribution
n_n_10
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_10
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_10




Gamma energy distribution
n_n_11
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_11
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_11




Gamma energy distribution
n_n_12
probability
0
20
40
60
80
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_12
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_12




Gamma energy distribution
n_n_13
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_13
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_13




Gamma energy distribution
n_n_14
probability
100
80
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_14
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_14




Gamma energy distribution
n_n_15
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_15
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_15




Gamma energy distribution
n_n_16
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_16
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_16




Gamma energy distribution
n_n_17
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_17
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_17




Gamma energy distribution
n_n_18
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_18
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_18




Gamma energy distribution
n_n_19
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_19
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_19




Gamma energy distribution
n_n_20
probability
80
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_20
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_20




Gamma energy distribution
n_n_21
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_21
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_21




Gamma energy distribution
n_n_22
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_22
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_22