
Main Cross Sections
Elastic
Capture
Inelastic
cross section (barn)
neutron energy(eV)
10^2
10^1
10^0
10^-1
10^-2
10^-3
10^-4
10^-5
10^-6
10^-7
10^-5 10^-4 10^-3 10^-2 10^-1 10^0 10^1 10^2 10^3 10^4 10^5 10^6 10^7 10^8


Cross Section
n_a_0
n_a_1
n_a_2
n_a_tot
cross section (barn)
neutron energy(eV)
10^-2
10^-4
10^-6
10^-8
10^-10
10^-12
10^-14
10^-16
10^-5 10^-4 10^-3 10^-2 10^-1 10^0 10^1 10^2 10^3 10^4 10^5 10^6 10^7


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_x
n_2n
n_3n
n_na
n_2na
n_np
n_nd
10^0
10^-2
10^-4
10^-6
10^-8
10^-10
10^-12
10^-14
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_2np
n_2a
n_2p
n_pa
n_n_1
n_n_2
n_n_3
10^0
10^-2
10^-4
10^-6
10^-8
10^-10
10^-12
10^-14
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20


Cross Section
cross section (barn)
10-1
10-2
10-3
10-4
10-5
10-6
n_n_4
n_n_5
n_n_6
n_n_7
n_n_8
n_n_9
n_n_10
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_n_11
n_n_12
n_n_13
n_n_14
n_n_15
n_n_16
n_n_17


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_n_18
n_n_19
n_n_20
n_n_cont
n_n_tot
n_p_0
n_p_1


Cross Section
cross section (barn)
10-3
10-5
10-7
10-9
10-11
10-13
10-15
10-17
n_p_2
n_p_3
n_p_4
n_p_5
n_p_6
n_p_7
n_p_8
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_p_9
n_p_10
n_p_cont
n_p_tot
n_d_0
n_d_1
n_d_2
10^-2
10^-4
10^-6
10^-8
10^-10
10^-12
10^-14
10^-16
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_d_3
n_d_4
n_d_5
n_d_cont
n_d_tot
n_t_0
n_t_1


Cross Section
cross section (barn)
10-3
10-5
10-7
10-9
10-11
10-13
10-15
10-17
n_t_2
n_t_3
n_t_4
n_t_5
n_t_cont
n_t_tot
n_He3_0
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Cross Section
cross section (barn)
10-6
10-8
10-10
10-12
10-14
10-16
10-18
10-20
n_He3_1
n_He3_2
n_He3_3
n_He3_4
n_He3_5
n_He3_cont
n_He3_tot
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Cross Section
cross section (barn)
10-3
10-5
10-7
10-9
10-11
10-13
10-15
10-17
n_a_0
n_a_1
n_a_2
n_a_3
n_a_4
n_a_5
n_a_6
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Cross Section
cross section (barn)
10-2
10-4
10-6
10-8
10-10
10-12
10-14
10-16
n_a_7
n_a_8
n_a_9
n_a_10
n_a_cont
n_a_tot
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^6
neutron energy(eV)


Angular distribution (CMS)
Elastic
probability
10^{1}
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_x part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2n part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2n part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_3n part.=neutron
probability
10^0
1.0 0.5 0.0 -0.5 -1.0
cos(theta)
0
40
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_3n part.=gamma
probability
10^0
1.0 0.5 0.0 -0.5 -1.0
cos(theta)
0
40
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_na part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_na part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_na part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2na part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
17
18
19
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2na part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
17
18
19
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2na part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
17
18
19
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_np part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_np part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_np part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_nd part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
17
18
19
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_nd part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
17
18
19
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_nd part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
17
18
19
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2np part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
19.0
19.5
20.0
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2np part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
19.0
19.5
20.0
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2np part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
19.0
19.5
20.0
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2a part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2a part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2p part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_2p part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_pa part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_pa part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_pa part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_1 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_1 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_2 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_2 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_3 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_3 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_4 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_4 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_5 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_5 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_6 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_6 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_7 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_7 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_8 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_8 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_9 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_9 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_10 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_10 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_11 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_11 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_12 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_12 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_13 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_13 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_14 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_14 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_15 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_15 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_16 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_16 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_17 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_17 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_18 part.=neutron
probability
10^0
1.0 0.5 0.0 -0.5 -1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_18 part.=gamma
probability
10^0
1.0 0.5 0.0 -0.5 -1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_19 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_19 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_20 part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_20 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_cont part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_0
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_1 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_1 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_2 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_2 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_3 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_3 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_4 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_4 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_5 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_5 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_6 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_6 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_7 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_7 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_8 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_8 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_9 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_9 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_10 part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_10 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_cont part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_p_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_0
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_1 part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_1 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_2 part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_2 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_d_3 part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_d_3 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_d_4 part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_d_4 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_5 part.=deuteron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_d_5 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_d_cont part.=deuteron
probability
10^0
1.0 0.5 0.0 -0.5 -1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_d_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
neutron energy (eV)
*10^6


Angular distribution (CMS)
n_t_0
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_1 part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_1 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_2 part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_2 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_3 part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_3 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_4 part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_4 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_5 part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_5 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_cont part.=triton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_t_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
12
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_0
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_1 part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_1 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_2 part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_2 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_3 part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_3 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_4 part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_4 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_5 part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_5 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_cont part.=3He
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_He3_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
16
18
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_0
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_1 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_1 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_2 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_2 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_3 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_3 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_4 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_4 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_5 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_5 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_6 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_6 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_7 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_7 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_8 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_8 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_9 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_9 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_10 part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_10 part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_cont part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_a_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_x part.=neutron
probability
10^{1}
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_x part.=proton
probability
10^{1}
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_x part.=deuteron
probability
10^{1}
10^{-1}
0
5
10
15
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_x part.=triton
probability
10^{1}
10^{-1}
0
energy (eV)
5
10
15
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_x part.=3He
probability
10^{1}
10^{-1}
2
4
6
8
10
12
energy (eV)
*10^6
0
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_x part.=alpha
probability
10^1
10^-1
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_x part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2n part.=neutron
probability
10^0
10^-2
0
5
10
15
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2n part.=gamma
probability
10^0
10^{-2}
0
1
2
3
4
5
*10 6
energy (eV)
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_3n part.=neutron
probability
10^1
10^0
0.0
0.5
1.0
1.5
energy (eV)
*10^6
0
40
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_3n part.=gamma
probability
10^1
10^0
0
200
400
600
800
1000
energy (eV) *10^3
0
40
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_na part.=neutron
probability
10^{1}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_na part.=alpha
probability
10^{1}
10^{-1}
0
5
10
15
energy (eV)
*10^6
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_na part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
1
2
3
*10 6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2na part.=neutron
probability
10^{1}
10^{-1}
0.0 0.5 1.0 1.5 2.0 2.5
energy (eV) *10^6
17 18 19 20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_2na part.=alpha
probability
10^{1}
10^{-1}
0
2
4
6
*10^6
energy (eV)
17
18
19
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2na part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
17
18
19
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_np part.=neutron
probability
10^{1}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_np part.=proton
probability
10^{1}
10^{-1}
0
2
4
6
8
10
12
energy (eV)
*10^6
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_np part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
12
14
16
18
20
$*10^3$
$*10^6$
energy (eV)
neutron energy (eV)


Energy distribution (CMS)
n_nd part.=neutron
probability
10^0
10^{-2}
0
energy (eV)
1
2
3
*10 6
17
18
19
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_nd part.=deuteron
probability
10^{1}
10^{-1}
0
2
4
6
*10^6
energy (eV)
17
18
19
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_nd part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0.0
0.5
1.0
1.5
energy (eV)
*10^6
17
18
19
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_2np part.=neutron
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
19.0
19.5
20.0
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2np part.=proton
probability
10^1
10^0
0.0
0.5
1.0
1.5
2.0
2.5
*10^6
energy (eV)
19.0
19.5
20.0
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2np part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0.0
0.5
1.0
1.5
*10^6
energy (eV)
19.0
19.5
20.0
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2a part.=alpha
probability
10^{1}
10^{-1}
0
5
10
15
energy (eV)
*10^6
10
12
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_2a part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
1
2
3
energy (eV)
*10^6
10
12
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_2p part.=proton
probability
10^{1}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_2p part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
1
2
3
4
*10 6
energy (eV)
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_pa part.=proton
probability
10^{1}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_pa part.=alpha
probability
10^{1}
10^{-1}
0
2
4
6
8
10
14
energy (eV)
*10^6
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_pa part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0.0
0.5
1.0
1.5
2.0
2.5
*10^6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_1 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_1 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
0
energy (eV) *10^3
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_2 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_2 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
0
5
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_n_3 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_3 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
0
5
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_n_4 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_4 part.=gamma
probability
10^1
10^0
0
200
400
600
800
1000
energy (eV) *10^3
0
5
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_n_5 part.=neutron
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_5 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_6 part.=neutron
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_6 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_7 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_7 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_8 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_8 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_9 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_9 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_10 part.=neutron
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_10 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
2.0
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_11 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_11 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
2.0
energy (eV)
*10^6
0
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_n_12 part.=neutron
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_12 part.=gamma
probability
10^1
10^0
0.0 0.5 1.0 1.5 2.0 2.5
energy (eV) *10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_13 part.=neutron
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_13 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
0
energy (eV)
*10^6
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_n_14 part.=neutron
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_14 part.=gamma
probability
10^1
10^0
0.0 0.5 1.0 1.5 2.0 2.5
energy (eV) *10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_15 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_15 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_16 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_16 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_17 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_17 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_18 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_18 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_19 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_19 part.=gamma
probability
10^1
10^0
0
1
2
3
*10 6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_20 part.=neutron
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_20 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
2.0
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_cont part.=neutron
probability
10^{1}
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_cont part.=gamma
probability
10^{2}
10^{1}
10^{0}
10^{-1}
0
1
2
3
*10 6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_0
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_p_1 part.=proton
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_1 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
0
5
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_p_2 part.=proton
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_2 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_3 part.=proton
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_3 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_4 part.=proton
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_4 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_5 part.=proton
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_5 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_6 part.=proton
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_6 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_7 part.=proton
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_7 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_8 part.=proton
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_8 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
2.0
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_9 part.=proton
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_9 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
2.0
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_10 part.=proton
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_10 part.=gamma
probability
10^1
10^0
0.0
0.5
1.0
1.5
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_cont part.=proton
probability
10^{1}
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_p_cont part.=gamma
probability
10^2
10^1
10^0
0.0
0.5
1.0
1.5
2.0
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_d_0
probability
10^{1}
0
energy (eV)
5
10
15
*10^6
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_d_1 part.=deuteron
probability
10^{1}
0
energy (eV)
5
10
15
*10^6
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_d_1 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
5
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_d_2 part.=deuteron
probability
10^{1}
0
5
10
15
*10^6
energy (eV)
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_d_2 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_d_3 part.=deuteron
probability
10^{1}
0
5
10
15
*10^6
energy (eV)
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_d_3 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_d_4 part.=deuteron
probability
10^{1}
0
5
10
15
*10^6
energy (eV)
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_d_4 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_d_5 part.=deuteron
probability
10^{1}
0
5
10
15
energy (eV)
*10^6
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_d_5 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_d_cont part.=deuteron
probability
10^{1}
10^{-1}
0
5
10
15
energy (eV)
*10^6
10
15
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_d_cont part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
10
15
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_t_0
probability
10^{1}
0
energy (eV)
5
10
15
*10^6
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_t_1 part.=triton
probability
10^{-1}
0
2
4
6
8
10
12
energy (eV)
*10 6
10
12
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_t_1 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
10
12
14
16
18
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_t_2 part.=triton
probability
10^{-1}
0
2
4
6
8
10
*10^6
energy (eV)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_2 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
*10^6
energy (eV)
10
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_3 part.=triton
probability
10^{-1}
0
2
4
6
8
10
12
*10^6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_3 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
*10^6
energy (eV)
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_4 part.=triton
probability
10^{-1}
0
2
4
6
8
10
12
energy (eV)
*10^6
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_t_4 part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
*10^6
energy (eV)
12
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_5 part.=triton
probability
10^{-1}
0
2
4
6
8
10
12
*10^6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_5 part.=gamma
probability
10^2
10^1
energy (eV) *10^3
800
1000
1200
1400
1600
1800
12
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_t_cont part.=triton
probability
10^{1}
10^{-1}
0
2
4
6
8
10
12
*10^6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_t_cont part.=gamma
probability
10^{2}
10^{1}
10^{0}
10^{-1}
0.0
0.5
1.0
1.5
energy (eV)
*10^6
12
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_He3_0
probability
10^{1}
0
energy (eV)
2
4
6
8
10
*10^6
14
16
neutron energy (eV)
18
20
*10^6


Energy distribution (CMS)
n_He3_1 part.=3He
probability
10^{1}
0
energy (eV)
2
4
6
8
10
*10^6
14
16
neutron energy (eV)
18
20
*10^6


Energy distribution (CMS)
n_He3_1 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
14
16
18
20
$*10^6$
energy (eV) $*10^3$
neutron energy (eV)


Energy distribution (CMS)
n_He3_2 part.=3He
probability
10^{-1}
2
4
6
8
*10 6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_He3_2 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
14
16
18
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_He3_3 part.=3He
probability
10^{-1}
2
4
6
8
*10 6
energy (eV)
14
16
18
20
*10⁶
neutron energy (eV)


Energy distribution (CMS)
n_He3_3 part.=gamma
probability
10^2
10^1
0
200
400
600
800
1000
energy (eV) *10^3
14
16
18
20
neutron energy (eV) *10^6


Energy distribution (CMS)
n_He3_4 part.=3He
probability
10^{1}
0
energy (eV)
2
4
6
8
*10 6
14
16
neutron energy (eV)
18
20
*10⁶


Energy distribution (CMS)
n_He3_4 part.=gamma
probability
10^2
10^1
0.0
0.5
1.0
1.5
energy (eV)
*10^6
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_He3_5 part.=3He
probability
10^{1}
0
2
4
6
8
*10 6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_He3_5 part.=gamma
probability
10^2
10^1
200 400 600 800 1000
energy (eV) *10^3
14
16
18
20
neutron energy (eV)
*10^6


Energy distribution (CMS)
n_He3_cont part.=3He
probability
10^{1}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
16
18
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_He3_cont part.=gamma
probability
10^1
10^0
10.0
0.5
1.0
1.5
16
energy (eV)
*10^6
18
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_a_0
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_1 part.=alpha
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_1 part.=gamma
probability
10^2
10^1
energy (eV) *10^3
0
200
400
600
800
1000
neutron energy (eV)
5
10
15
20
*10^6


Energy distribution (CMS)
n_a_2 part.=alpha
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_2 part.=gamma
probability
10^2
10^1
energy (eV) *10^3
0
200
400
600
800
1000
neutron energy (eV)
5
10
15
20
*10^6


Energy distribution (CMS)
n_a_3 part.=alpha
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_3 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_4 part.=alpha
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_4 part.=gamma
probability
10^1
10^0
0.5
1.0
1.5
2.0
2.5
0
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_5 part.=alpha
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_5 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
4
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_6 part.=alpha
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_6 part.=gamma
probability
10^1
10^0
0.5
1.0
1.5
2.0
2.5
0
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_7 part.=alpha
probability
10^{1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_7 part.=gamma
probability
10^1
10^0
1600
800
1000
2000
4000
6000
0
energy (eV) *10^3
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_8 part.=alpha
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_8 part.=gamma
probability
10^1
10^0
0
1
2
3
4
*10 6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_9 part.=alpha
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_9 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_10 part.=alpha
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_10 part.=gamma
probability
10^1
10^0
0
energy (eV)
1
2
3
*10 6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_cont part.=alpha
probability
10^1
10^-1
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_a_cont part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
1
2
3
4
*10 6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)